Potential Health Effects from HVP Products Exposure

SKIN Irritation of skin may occur and progress to

dermatitis. One component, benzene, may be absorbed through the skin.

Irritation of eyes may occur. **EYES**

Breathing mists or vapours may cause accumulation BREATHING in the lungs and/or central nervous system depression,

dizziness, headaches, giddiness, drowsiness, fatique,

nausea, unconsciousness or death.

Swallowing mists or vapours may cause accumulation **SWALLOWING** in the lungs and/or central nervous system depression,

dizziness, headaches, giddiness, drowsiness, fatique,

nausea, unconsciousness or death.

Defatting and drying of skin may occur and cause LONG-TERM HAZARDS

dermatitis. Inhalation of one component, benzene. has been associated with blood disorders including anemia and leukemia. Repeated exposure to high vapour concentrations may cause eye and respiratory

irritation, giddiness, staggered gait, nausea, abdominal pain, loss of appetite, liver damage, kidney damage, and damage to the bone marrow including

CARCINOGENICITY

Benzene is listed with IARC, NTP, ACGIH or OSHA

as a carcinogen.

Response Consideration

Environment, Health & Safety

Plains adheres to the highest environmental and safety standards throughout our organization. We provide a workplace that protects the health and safety of our employees, contractors and the communities surrounding our facilities.

Plains' operations are subject to stringent federal, provincial and local laws and regulations governing the discharge of materials into the environment or otherwise related to protecting the environment.

Our Environment, Health and Safety (EH&S) Management Programs are at the core of our operations. These programs include management commitment and leadership, employee training and awareness, inspections and audits, performance and achievement recognition, emergency preparedness and response, communications and continuous improvement.

Notification

If you are contacted by Plains Midstream Canada to advise you of an emergency situation, the caller will:

- Identify themselves by name.
- Announce that they are a Plains Midstream Canada representative.
- Describe the problem and what is being done.
- Give you instructions to protect your safety (shelter / evacuation).
- Verify the information you have provided.
- Address any concerns which you may have.
- Provide a telephone number which you can call to get additional information.

Emergency Contacts

If you suspect a problem at a Plains facility in your area, please call Plains Midstream Canada's 24-hour Emergency Response number:

1-866-875-2554

In the event of an emergency, Plains will be working with the Alberta Energy Regulator and the local authority.

Alberta Energy Regulator (AER)

AER 24-hour emergency line 1-800-222-6514

Saskatchewan Ministry of Energy and Resources (ER)

Local Authority

Cypress County	
RM of Deer Forks No.232	



Pipeline Safety Keeping Pipelines Safe and Reliable



Public Awareness Information for landowners and area residents related to Plains Midstream Canada's Empress 1 - 5 Plant.

- Emergency notification
- Public protection measures

MARCH 2022



Operations in your Area

Plains Midstream Canada ULC (Plains) is the operator of the Empress 1-5 Plant within Cypress County. The Empress 1-5 Plant includes the storage of NGL's which is classified as High Vapour Pressure (HVP). As these storage tanks a contain substances in excess of threshold limits listed in Schedule 1 of the Canadian Environmental Protection Act (CEPA), an Environmental Emergency (E2) plan has been developed for the Empress 1-5 Plant to meet Environment and Climate Change Canada Environmental Emergency Regulations, 2019: SOR/2019-51. Included below is the calculated Emergency Planning Zones (EPZ) , including the substances stored at the facility. Refer to the map on the back of this brochure for more details.

PMC Empress 1-5 Plant 04-12-20-01 W4M E2 Regulated Substances: Propane, NGL Emergency Planning Zone: 200 m

High Vapour Pressure (HVP) Products

HVP products include propane, butane, pentane, and Natural Gas Liquids (NGLs). At atmospheric pressure, HVP products are gases. Under pressure, HVP products exist in a liquid state. In humid air, a leak of an HVP product may form a visible white cloud of cold vapour considerably heavier than air. Under extreme conditions, pools of super-cooled liquid may briefly form. When HVP products vapourize, they expand (70 to 300 times) and can form a plume, which may drift downwind from the source under moderate wind speed conditions. Under higher wind speed conditions, the vapour would dissipate faster.

Main Hazards:

- Potential explosion hazards from delaying ignition of drifting vapour cloud.
- Fire hazard from burning gas and radiant heat.
- Critical hazard because of oxygen deficiency as expanding gas cloud or plume displaces air at ground level.

If You Suspect a Problem

Please call Plains Midstream Canada's 24-hour emergency number if you suspect a problem (1-866-875-2554).

While the chance of an uncontrolled spill or problem is remote, the Plains Emergency Response Plan (ERP) for this area is in place to ensure your safety. If a leak should occur, emergency crews will take immediate steps to minimize the risk to the public and environment.

Additional emergency response personnel will be notified and dispatched to the area to safely manage the emergency.

Public Protection Measures Evacuation, Shelter & Ignition Procedures

Evacuation Procedures

If it is necessary to evacuate, you will be contacted by telephone immediately. If there is no answer to our calls, we will proceed to your residence to inform you of the situation. The following steps should be taken if "Evacuation" procedures have been implemented:

- Gather all residents and bring any medicines required.
- Lock all windows and doors.
- Turn down thermostat and shut off any air exchange fans to outside.
- Drive safely on the route provided and proceed directly to the evacuation centre and check in with the representative.
- Wait for further instruction.

Shelter-in-Place Procedures

If you are advised to stay sheltered, do not leave your house or attempt to start any vehicles until a Plains representative advises you that it is safe to do so. The following steps should be taken if "Shelter-In-Place" procedures have been implemented:

- Immediately gather everyone indoors and stay there.
- Tightly close and lock all windows and outside doors, if convenient, tape any gaps around exterior door frames.
- Extinguish indoor wood-burning fires and close flue dampers if possible.
- Turn off appliances or equipment that either blows out or uses indoor air, such as:
 - furnaces

- built-in vacuum systems
- gas stoves

kitchen fans

bathroom fans

• clothes dryers

air conditioning

gas fireplaces

- ventilators
- Turn off appliances or equipment that suck in outdoor air, such as
 - Heating, ventilation, and air conditioning (HVAC) systems
 - Fans for heat recovery ventilators or energy recovery ventilators
 - Turn down furnace thermostats to the minimum setting, turn off air conditioners
- Leave all inside doors open.
- Wait in an interior room upstairs for further instruction.
- Avoid using the telephone, except for emergencies, so that you can be contacted by Plains emergency response personnel.
- Call Plains if you are experiencing symptoms, smelling odours or have contacted government agencies (so the response can be coordinated).
- Stay tuned to local radio and television for possible information updates.
- Even if you see people outside, do not leave until told to do so.
- If you are unable to follow these instructions, please notify Plains emergency response personnel.

After the hazardous substance has passed through the area you will receive an "all-clear" message from Plains emergency response personnel. You may also receive, if required, instructions to ventilate your building by:

- opening all windows and doors
- turning on fans

 turning up thermostats

During this time the air outside may be fresher and you may choose to leave your building while ventilating. Once the building is completely ventilated, return all equipment to normal settings and operation.

Ignition Procedures

If it is determined that ignition is required, the Incident Commander is fully authorized to ignite the release at the pipeline, facility or terminal. Ignition of the gas source would ensure your safety if evacuation was not practical.











